



Docket No.: 250599US90PCT

ATTORNEYS AT LAW

Certificate

SEP 0 9 2005

of Correction

COMMISSIONER FOR PATENTS ALEXANDRIA, VIRGINIA 22313

RE: Inventor: Yogo KAWASAKI, et al.

Patent No.: 6,930,258 Issued: August 16, 2005 Group Art Unit: 2841

Examiner: Ishwar (I.B.) Patel

For: MULTILAYER PRINTED WIRING BOARD AND

METHOD OF PRODUCING MULTILAYER

PRINTED WIRING BOARD

SIR:

Attached hereto for filing are the following papers:

## REQUEST FOR CERTIFICATE OF CORRECTION CERTIFICATE OF CORRECTION FORM PTO 1050

Our check in the amount of \$0.00 is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. A duplicate copy of this sheet is enclosed.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

<sup>4</sup> Masayasu Mori

Registration No. 47,301

Roland E. Martin Registration No. 48,082

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 05/04) DOCKET NO.: 250599US90PCT/hse



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Yogo KAWASAKI, et al.

PATENT NO.: 6,930,258

GROUP: 2841

ISSUED: August 16, 2005

EXAMINER: Ishwar (I.B.) Patel

FOR: MULTILAYER PRINTED WIRING BOARD AND METHOD OF PRODUCING

MULTILAYER PRINTED CIRCUIT BOARD

## REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a request for a Certificate of Correction in Serial Number 09/830,963, now Patent Number 6,930,258.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the Patent Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the Patent Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully Submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, P.C.

Masayasu Mori

Registration No. 47,301

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 05/05) Roland E. Martin Registration No. 48,082 UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.:

6,930,258

DATED:

Aug. 16, 2005

INVENTOR(S):

KAWASAKI, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item 22, the PCT Filed date is incorrect. Item (22) should read:

--[22] PCT Filed: Oct. 10, 2000 --

Mailing address of sender:

Patent No.

6,930,258

Customer Number

22850

No. of add'l copies @ .30 per page

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 03/02)

**口**〉